0012



State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING



Michael O. Leavitt Governor Kathleen Clarke

Executive Director

Lowell P. Braxton

Division Director

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801

801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

INSPECTION REPORT

Partial: XXX	Complete:	Exploration:		
Inspection Date & 7	Гіте: <u>05/23/20</u>	01/10:00 am -12:00 pm		
	st Inspection: 04			

Mine Name: Savage Coal Terminal County: Carbon	Permit Number: <u>C/007/022</u>
Permittee and/or Operator's Name: Savage Industries, Inc.	
Business Address: 5250 South 300 West, Suite 200, SLC, UT 84107 /	PO Box 587, Wellington, Utah 84542
Type of Mining Activity: Underground Surface XXX	Prep. Plant Other
Company Official(s): Boyd Rhodes	
State Official(s): Joe Helfrich Federal Official(s): Non	<u></u>
Weather Conditions: Sunny 70's	
Existing Acreage: Permitted 160 Disturbed 122 Regrad	led Seeded
Status: Active XXX	

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	<u>N/A</u>	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	Ш
2.	SIGNS AND MARKERS	[X]	\Box		
3.	TOPSOIL	[X]	Ц	[X]	
4.	HYDROLOGIC BALANCE:				
	a. DIVERSIONS	\Box	\Box	П	
	b. SEDIMENT PONDS AND IMPOUNDMENTS	\Box	\Box	П	П
	c. OTHER SEDIMENT CONTROL MEASURES	[X]		[X] []	
	d. WATER MONITORING		\Box		
	e. EFFLUENT LIMITATIONS		\Box		П
5.	EXPLOSIVES	\Box	П		
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES		П		П
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		П	П	Ц
	NONCOAL WASTE	\Box	П	П	Ц
9.	PROTECTION OF FISH, WILDLIFE AND RELATED	\Box	\Box	Ш	Ш
	ENVIRONMENTAL ISSUES				
	SLIDES AND OTHER DAMAGE	\Box	\Box	П	Ц
11.	CONTEMPORANEOUS RECLAMATION	\Box	\Box		
	BACKFILLING AND GRADING	\Box	\Box	П	Ц
	REVEGETATION	П	П	Ц	
	SUBSIDENCE CONTROL	\Box	П	Ц	Ц
	CESSATION OF OPERATIONS	П	П	П	\Box
16.	ROADS:				r 1
	a. CONSTRUCTION/MAINTENANCE/SURFACING	П	Ц	Ц	Ц
	b. DRAINAGE CONTROLS	Π̈́		Ц	<u> </u>
	OTHER TRANSPORTATION FACILITIES	Ц	Ц		
	SUPPORT FACILITIES/UTILITY INSTALLATIONS	Ц	Ц	Ц	L 3
	AVS CHECK (4th Quarter- April, May, June)	Π̈́	Ц		
	AIR QUALITY PERMIT	Ц	Ц	<u> </u>	H
21	BONDING & INSURANCE		[]	П	\Box

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/007/022

DATE OF INSPECTION: <u>05/23/2001</u>

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The undersigned informed Boyd Rhodes that the Division had received the amendment to relocate the truck dump and the review was scheduled for the week of 5/28/2001. Mr. Rhodes was also appraised of the approval of the test plot removal amendment.

3. TOPSOIL

Possibilities of mixing refuse with soil on areas of the topsoil pile were discussed with Boyd. He was amenable to pursuing the idea.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

We visited the gabion structures located in the diversion on the North side of the property. The consensus was to rebuild the three lower ones and add another between the lower two.

Inspector's Signature:

Joseph C. Helfrich #

Date: May 24, 2001

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd cc:

James Fulton, OSM

James Jensen, Savage, SLC Boyd Rhodes, Savage, Price

Price Field office

O:\007022.SAV\Compliance\2001\P_0523.wpd